

UST Inspections Federal Facilities

- Pre-briefing with facility personnel
- Physical Inspection
- Records Review
- Out-briefing with Facility personnel

UST Inspections

- Physical Inspection
 - Tanks and piping
 - Spill containment
 - Overfill protection
 - Corrosion protection equipment
 - Corrective action implementation

UST Inspections

- Record Review
 - UST registration and permits from state implementing agency
 - Release Detection
 - Repairs
 - Corrosion Protection
 - Closure Records

UST Inspections

- Out-briefing with facility personnel
- Inspection report will be forwarded to facility head.
- Follow up information request (RCRA 9005)
- Enforcement action?

UST Inspections

Common Problems

- Equipment not used properly
- Facility staff not knowledgeable on proper use of equipment
- Monthly leak detection records not available
- Corrosion protection equipment not working
- Impressed current equipment not checked for proper operation every 60 days.
- Impressed current and galvanic (STIp3) systems not tested by qualified tester every 3 years.

UST Inspections

Common Problems

- Water and/or debris in spill bucket
- Overfill alarm not within sight or hearing distance
- Failure to report spills/overfills > 25 gallons

UST Inspections

More information or help

- State implementing agency
- hollinger.mike@epa.gov (404) 562-9469
- miller.mallory@epa.gov (404) 562-9483